

Bradmore Footpaths

No	Description	F/B	Stiles/Gates	Condition of Path	Condition of Stiles	Work done/ needed by me	Work Needed by CC	Date last walked
1	Mill Lane to Half Way Barn Farm to Flawforth Lane	B	-	Fine and dry	N/A	-	-	10 October 2018
2	Country Park Road to gate onto Little Moor Lane	F	Gate with Little Moor Lane (2a).	Fine	Gatepost completely broken and removed - now a gap	-	Looks like gate will just be a gap in future	20 August 2018
3	Little Moor Lane through Horse Field 1 ("HF1"), turning at Horse Field 2 ("HF2") to cross Clay Field as far as bridleway	F	Kissing Gate at top HF1 (3a) Kissing Gate HF1 to HF2 (3b) Gate HF2 to Clay Field (3c)	Field lightly ploughed as is path	Gate HF2 to Clay field won't shut to latch. If anything this is fitting even worse but protected from horses by small electric fence.	-	-	05 October 2018
4	Main Bridleway from village to Syd's bench	B	Gate into HF2 (4a)	In good condition	Post on (4a) broken by horses. Mended and gate shut with bridle. NCC aware. Protected by electric fence.	-	-	30 October 2018
5	From 4 through gate across Horse Field 3 across stile into grass field then across stiles via two fields to bridge	F	Kissing Gate at top HF3 (5a) Stile bottom HF3 (5b) Kissing Gate edge of grass field (5c) Stile next field (5d) Bridge (5e)	Crop now cut so path passable again	Stiles covered in expamet. Plank broken on exit from from (5b)	-	Repairing of decking at (5b). Have chased NCC - no action action will chase again	06 October 2018
6	From 8, across HF3 to stile at bottom across grass field to gap in hedge at Syd's bench	F	Stile bottom HF3 (5b)	Crop now cut so path passable again	Stiles now covered in expamet. See broken plank comment above	-	Clear waymark posts installed through field by NCC. One broken	06 October 2018
7	Farmer Street (Toft's end) path between houses then on to Rancliffe House	F	Gate on leaving village (7a) Gate onto field to Rancliffe Ho (7b) Stile at end of field (7c)	Path cut as part of regular cutting of field	Stile good.	Path good and clear	-	27 August 2016
8	Loughborough Road through gate past sheep field through small horse field to Horse Field 3.	F	Gate at end of sheep field (8a) Kissing Gate to HF3 (8b)	Good. High fence built by resident stops interaction (barking) between dogs	Good	-	-	27 August 2018

