

# Bradmore Footpaths

| No | Description  | F/B | Stiles/Gates   | Condition of Path  | Condition of Stiles  | Work done/ needed by me   | Work Needed by CC  | Date last walked |
|----|--|-----|--|--|--|---|--|------------------|
| 1  | Mill Lane to Half Way Barn Farm to Flawforth Lane  | B   | -  | Some mud on road   | N/A  | -   | -  | 10 August 2016   |
| 2  | Country Park Road to gate onto Little Moor Lane  | F   | Gate with Little Moor Lane (2a).   | Farmer now cut path Initially clods of earth from ploughing but seems to be OK   | OK   | Nettles cut around gate on 7th August                                 | -  | 06 August 2016   |
| 3  | Little Moor Lane through Horse Field 1 ("HF1"), turning at Horse Field 2 ("HF2") to cross Clay Field as far as bridleway | F   | Kissing Gate at top HF1 (3a)<br>Kissing Gate HF1 to HF2 (3b)<br>Gate HF2 to Clay Field (3c)  | Clay Field now dry (ish)   | Gate HF2 to Clay field won't shut to latch. If anything this is fitting even worse but protected from horses by small electric fence | Nettles around gate and brambles around bottom gate cut on 7th August | -  | 07 August 2016   |
| 4  | Main Bridleway from village to Syd's bench   | B   | Gate into HF2 (4a)   | Descent a bit rutted. Some glass around from original hardcore. Warning sign in place.   | Post on (4a) broken by horses. Mended and gate shut with bridle. NCC aware. Protected by electric fence.                             | Nettles cut around bench and gate 4a on 7th August                    | 2nd cut on bridleway mid August  | 30 August 2016   |
| 5  | From 4 through gate across Horse Field 3 across stile into grass field then across stiles via two fields to bridge       | F   | Kissing Gate at top HF3 (5a)<br>Stile bottom HF3 (5b)<br>Kissing Gate edge of grass field (5c)<br>Stile next field (5d)<br>Bridge (5e) | Good. Reasonably dry for the time of year.   | Mud under gate 5c now dry. Stiles now covered in expamet   | -   | -  | 27 August 2016   |
| 6  | From 8, across HF3 to stile at bottom across grass field to gap in hedge at Syd's bench                                  | F   | Stile bottom HF3 (5b)  | Horse field lightly ploughed for grass seeding. Paths have effectively diverted to one from Syd's bench to 5c and one round the field. | Good   | Nettles cut 7th August  | Clear waymark posts installed through field by NCC. One already broken | 27 August 2016   |
| 7  | Farmer Street (Toft's end) path between houses then on to Rancliffe House  | F   | Gate on leaving village (7a)<br>Gate onto field to Rancliffe Ho (7b)<br>Stile at end of field (7c)                                     | Path cut as part of regular cutting of field   | Stile good. Tree now cleared by NCC  | Path good and clear   | Tree clearance. Now done by NCC  | 27 August 2016   |
| 8  | Loughborough Road through gate past sheep field through small horse field to Horse Field 3.                              | F   | Gate at end of sheep field (8a)<br>Kissing Gate to HF3 (8b)  | Good   | Good   | Path good and clear   | -  | 27 August 2016   |

